EG&G ROCKY FLATS



000013666

INTEROFFICE CORRESPONDENCE

DATE:

October 6, 1993

T0:

D. L. Schubbe, Remediations Projects Mamt., Bldg. 080, X8709

m.o.s.

FROM:

M. D. Schreckengast, Industrial Hygiene, Bldg. T452G, X6790

SUBJECT:

BERYLLIUM SMEAR RESULTS FOR BUILDING 883, ROOM 104 - MDS-013-93

This letter details results of the beryllium smear surveys collected in Building 883, Room 104 (Individual Hazardous Substance Site [IHSS] 104). 150

On August 25, 1993, 54 smears were collected by Radiological Operations during the initial pre-job survey (see Attachment 1 for the map and Attachment 2 for smear results). Four of these 54 smears taken indicated beryllium above the beryllium smear control level of 25 micrograms per square foot (ug/ft²), as stipulated in the Rocky Flats Plant Beryllium Protection Program, 1-15310-HSP-13.04.

On August 26, 1993, the second pre-job survey was conducted by Radiological Operations. Prior to this survey, the survey grid pattern was altered to include 49 square meter areas instead of 55 (see Attachment 3 for the map and Attachment 4 for smear results). Five of the 49 smears indicated beryllium above the beryllium smear control level.

On September 7, 1993, the post-job smear survey was performed by Radiological Operations. Nine of the 49 smears indicated significantly higher levels of beryllium (see Attachment 5).

Because post-job survey smears indicated beryllium levels above 25 ug/ft², building personnel are required to decontaminate the area and re-smear for beryllium. R. T. Stagner, 883 Building Manager, has been notified of these requirements.

If you have any questions regarding this matter, please feel free to call me.

vgm

Attachments: As Stated

J. M. Brooks of for JMS B. M. C.

B. M. Clausen J. G. Kroll

0. McAfee

L. A. Nelowet

D. R. Sweet

G. T. Ostolek

LEGIG ROCKY FLATS

INTEROFFICE CORRESPONDENCE

DATE:

October 5, 1993

T0:

R. T. Stagner, 800 Area Operations, Bldg. 881, X5395

mis.

FROM:

M. D. Schreckengast, Industrial Hygiene, Bldg. T452G, X6790

SUBJECT:

BERYLLIUM SMEAR RESULTS FOR BUILDING 883, ROOM 104 - MDS-012-93

INTRODUCTION:

Within the past few months, Phase I RFI/RI (Resource Conservation and Recovery Act [RCRA] Facility Investigation [RFI]/ Remedial Investigation [RI]) work has begun on the Operable Unit (OU) 15 project. Included in OU 15 is the drum storage area deemed Individual Hazardous Substance Site (IHSS) 180, in Building 881, Room 104. Phase I work involves several activities in each of the IHSSs, including an initial pre-job smear survey, a second pre-job smear survey, hot rinsate sampling, and a post-job smear survey. Because building 883 has been involved with beryllium in the past, all smears were analyzed for beryllium. This letter details those results.

CONCLUSION:

All three smear surveys indicated beryllium levels above the 25 micrograms per square foot ($\mu g/ft^2$) beryllium smear control level. This area must be decontaminated and re-smeared in order to verify beryllium removal.

FINDINGS/DISCUSSION:

On August 25, 1993, Radiological Operations conducted the initial pre-job survey at IHSS 180 in Building 883, Room 104. The area of study was divided into 55 square meters, 1-54 were smeared. Please refer to the map provided in Attachment 1 and the results provided in Attachment 2. After this survey, the grid pattern was altered and 49 square meter areas instead of 55 were identified for sampling.

On August 26, 1993, Radiological Operations conducted the second pre-job survey. Please refer to the map provided in Attachment 3 and the results provided in Attachment 4.

R. T. Stagner October 6, 1993 MDS-012-93 Page 2

After this survey, hot rinsate sampling was performed by ERM-Rocky Mountain over all 49 identified sample square meter areas. Last, the post-job smear survey was conducted by Radiological Operations on September 7, 1993. Please refer to the results provided in Attachment 5.

The Rocky Flats Plant Beryllium Protection Program, 1-15310-HSP-13.04, establishes 25 $\mu g/ft^2$ as the beryllium smear control level. Four smears from the initial pre-job survey, five from the second pre-job survey, and nine from the post-job survey indicated beryllium levels above the 25 $\mu g/ft^2$ beryllium smear control level. Results from the three surveys are not consistent as to location of contamination. Reasons for these discrepancies may include current building foot traffic spreading/moving contamination, different locations of the 100 square centimeter smear areas inside the square meter areas, etc.

Procedure 1-15310-HSP-13.04 requires that areas having levels above 25 $\mu g/ft^2$ be decontaminated, and then re-smeared and re-counted for beryllium. Please mark the area with tape, barriers, etc., to eliminate spread of the contamination; and arrange for decontamination and another smear survey to verify decontamination.

Employees involved in the decontamination must have completed Beryllium Operations Training within the past two years. Personal protective equipment requirements for decontamination include: 1) a half-mask or full-face respirator equipped with high efficiency particulate (HEPA) cartridges, 2) tyvek coveralls worn over whites, and 3) surgeons gloves.

If you have any questions or concerns, please contact me at Extension 6790.

vgm

Attachments:

As Stated

cc w/o Att:

J. M. Brooks

B. M. Clausen

L. A. Holwager, Jak


J. G. Kroll/K

McAfee - w/Att

L. A. Nelowet

D. L. Schubbe

D. R. Sweet



2 () C	LI AIN SAMPLE SMEAR SAMPLE SPECIAL SAMPLE	LE 883 S/AZW		ROCKY FLATS PLANT	IS PLANT			Se	and Result X 2780	ts To INDU	Send Results To INDUSTRIAL HYGIENE X 2780	YGIENE .
10 24 24	7		96	RYLLIUM SAMPLE LOG	AMPLE LO	90						· •, ·
	- (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	1 - (100.381)	. Date Collected:	ited: S	8-25-73 TE		TIME			ت	Lab No. 6	444
SAMPLE NO.	BLDG. ROOM		NOI	NO	OFF	NO	OFF	AT MIN	FLOW RATE	VOL OR AREA	SAMP'LE	14/ ft.
	353 104	See a theelied myp	MY	N	NIM	NIA	NA	N/A	мIn	NETWE	_ >	610
								_		100cm²	->	410
~\ <u></u>												Ó1.>
7												\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
											->	V.10
											7	710
90												
7												(Si >
7.7)												
											- i	(5)
(1,2)												() ()
, %											1>	015
7:7											\ \ \	ÇIÇ
<;;											1.>	(10
11/		***************************************									17	210
			Li de la companio de									SID.
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\									+			(10)
7.7									_		\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.	210
2,1									+	1	17	(10)
2.2									1			015
									+			7 (1)
-												
2.	<u> </u>			,			->	_>	.		7	Atta MDS- Page
RF 28990 (£	RF 28990 (9/85) MHS 11-3.2		INDUSTI	STRIAL HYGIENE COPY	SIENE CC	Ъγ				Page 1		chment: 013-93 1 of 3
										(0 . 1		3

لبت	3 SMEAR	[] SMEAR SAMPLE		11000	HOUNT LENIOTEMM			Se	and Hesul	S TO INDO	Send Results TO INDUSTRIAL ITEME	GIENE
ų.]SPECIA	-E SPECIAL SAMPLE	E 385 2000111			(X 2780			
•				BEHYLLIUM SAMPLE LOG	A SAMPLE	L0G					`	
NAME			Da	Date Collected: _	\$	8-25-93				ت	Lab No 5	6.44
101110	4				DATE	F	TIME	ŀ	i			747
SAMPLE NO.	BLDG.	ROOM		NO	I OFF	NO	OFF	N N	FLOW RATE	VOL OR AREA	SAMI".E µg	tracting the state of the state
22	383	104	See albahad map	FILL IN	A NA	NA	UN	NIA	NA	~ COoni	ز.	56
\S.\.				-	<u> </u>		- 1		!		~	410
23									/		$\overline{\lor}$	(3) >
30		:									./) () ()
· Y											<u> </u>	<10
555												\ \ \ \ \ \
d)	:										~	SID.
7.5	:										~	01>
35											<u> </u>	() >
											<u>\</u>	() >
C 37			V								.بر:	38
			Theo the scale						ļ			10
25											<u> </u>)
40		:		4		, —					1>	<1Ü.
17>												<10
45			Mean The Alake								1	SIÜ.
4 7 3											0/	93
		-									(0)	93
											\ \ \ \	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
											\ \\	<u> </u>
(-)-				- 1.00 May 100							\ \ \	SIU
											21	13
44) >	O</td
50		:									./	<u> </u>
[V]											4.	<1Ü
55		->		<i>Y</i>		<u></u>	.>	-	,	_>	K /	<1Û
RF-28990	RF-28990 (9/85) MHS 11-3.2	15 11-3.2		INDUSTRIAL HYGIENE COPY	HYGIENE	СОРУ			ž	Page	5 of 3	i.

 $\mu g/m^3$ Send Results To INDUSTRIAL HYGIENE 410 Lab No. 5/6/6/ VOL OR SAMΓ'LE AREA μθ N/A ICOUNT NIA NA ICOCON X 2780 FLOW N Δ1 MIN OFF TIME INDUSTRIAL HYGIENE COPY BERYLLIUM SAMPLE LOG ROCKY FLATS PLANT DATE Date Collected: See attached map DESCRIPTION DAIR SAMPLE


SMEAR SAMPLE

SPECIAL SAMPLE

SSS 500010 NAME C/QUEN/ KING 883 104 883 104 HF-28990 (9/85) MHS 11-3.2

P

<u>(</u>



Attachment 4 MDS-013-93 Page 1 of 2 180 m $\mu g/m^3$ Send Results To INDUSTRIAL HYGIENE 410 2 S D (11) ζII) 380 3 SAMPLE 49 Lab No. VOL OR AREA 1Wem4 X 2780 FLOW RATE UN <u>e</u> ₽ MIN MIN OFF <u>U</u> TIME N NO INDUSTRIAL HYGIENE COPY BERYLLIUM SAMPLE LOG **ROCKY FLATS PLANT** Mn OFF DATE N NO Date Collected: See attached map. DESCRIPTION 883 Special - CISMEAR SAMPLE ROOM RF-28990 (9/85) MHS 11-3 2 883 104 LI AIB SAMPLE BLDG. NAME SAMPLE

Send Results To INDUSTRIAL HYGIENE µg/m³ \$10 \$10 \$10 (10 130 3 2 <u>410</u> (11) 012 2 \<u>\</u> **(10)** Lab No. 6/4/4 2 2 of 2 VOL OR SAMΓ'.E AREA μ9 100cm² X 2780 FLOW RATE N/A. NA MIN MIN OFF NN TIME <u>N</u>0 INDUSTRIAL HYGIENE COPY BERYLLIUM SAMPLE LOG Date Collected: 8-26-9 HUCKY FLATS PLANT NIA OFF DATE N/M NO DESCRIPTION See attached may BSMEAH SAMPLE 883 - Special ROOM 100 RF-28990 (9/85) MHS 11-3.2 883 BLDG. NAME SAMPLE

Attachment 5 MDS-013-93 Page 1 of 2 $\mu g/m^3$ Send Results To INDUSTRIAL HYGIENE 9 **S** 10 3 3 S/ID 3 StD 410 28 2 (11) 0 **()** Lab No. Bey ST VOL OR SAMFLE AREA #9 100em² X 2780 NA FLOW RATE OFF N TIME INDUSTRIAL HYGIENE COPY BERYLLIUM SAMPLE LOG ROCKY FLATS PLANT OFF NO Date Collected: i 3 SPECIAL SAMPLE 333 TAKEN 9/1/83 Su map. Appendix DESCRIPTION NAME DECMARC SMEAR SAMPLE ROOM RF-28990 (9/85) MHS 11-3.2 104 LI AIR SAMPLE BLDG. 383 583 SAMPLE NO. 5

 $\mu g/m^3$ × 10 111 30.7) 251 Send Results To INDUSTRIAL HEARENE 562 410 $\overline{\mathbb{C}}$ Lab No. Ben E. VOL OR SAMPLE AREA μθ 11.00 X 2780 FL.OW RATE N/N NU INDUSTRIAL HYGIENE COPY BERYLLIUM SAMPLE LOG HOCKY FLATS PLANT SZ Date Collected: KISPECIAL SAMPLE XX3 THKENL 9/1 173 See Map. Aprollin 3 DESCRIPTION (C/445er ROOM RF 28990 (9/85) MHS 11-3 2 NAME DERIVAC SAMPLE

(Hap 20/2